

Guardian Fall Protection 26609 79th Ave. S. Kent, WA 98032

Test Certificate

DATE: 6/26/2010	DESCRIPTION OF TEST: Per OSHA 1926.502(B)(3) The clamp was tested attached to the test bed with a 15175 42" Guardrail Post
CUSTOMER: Guardian Fall Protection	inserted to replicate actual usage scenarios and pulled to 200 lbs of force
PRODUCT PART # AND DESCRIPTION:	
15170 Parapet Clamp System with 15175 42" Guardrail Post	PROOF LOAD: N/A
BREAKING LOAD IF APPLICABLE:	
N/A	
	TEST MACHINE: Dillon AFTI Advanced Force Torque Indicator Serial # 122971/04-0005-10. S-beam load cell
LOCATION AND MANNER OF BREAK:	
N/A	DATE CALIBRATED:
	06/19/2010

REMARKS: The Parapet Clamp was attached to the test bed and a 42" Guardrail Post was inserted. The post was secure approximately 2" below the top and pulled to 225 lbs and held for a period of 3 minutes. After 3 minutes the force was increased to 400 lbs for an additional 3 minutes.

After testing the clamp assembly was visually inspected and showed no signs of deformation. The Guardrail post showed a slight bow after testing but all welds were secure and showed no visible signs weakening. This unit passed all requirements of the testing standard.

TEST CONDUCTED BY:

Larry Baker (Quality Assurance Director)